


EXPLANATION

- Head of Cash Entry shaft
- Head of raise or winze
- Foot of raise or winze
- Tunnel entrance
- Inclined workings (chevrons point down).
- 300 level
- 400 level
- 450 level
- Stope fill



PLAN AND SECTION OF CASH ENTRY MINE, CERRILLOS DISTRICT, NEW MEXICO
 (AFTER OLD MAP BY BOSTON-NEW MEXICO MINING COMPANY)