
Outcrop for ZP_06

Upper image: Sand and clay body thicknesses and lengths measured from 3D model.
Lower image: Contact length and texture-based polygons are measured in ArcMap.
View to the northeast.
Lithostratigraphic unit: Taob (Loma Barbon Member of Arroyo Ojito Fm.)
Hydrostratigrpahic unit: middle Middle Rio Rancho
UTM coordinates near center of image (NAD83, zone 13): 338275 m E, 3920540 m N




KEY (top):

- Location of contacts (undifferentiated)
- Length of sand or clayey body
- Thickness of sand or clayey body

KEY (bottom):

- Analyzed outcrop area
- Contact -- sand on sand
- Contact -- sand adjacent to clayey unit.
- Lithologic interpretation
- Contact -- Lateral gradation of sand into a clayey unit.



Outcrop for ZP_06

Upper image: Sand and clay body thicknesses and lengths measured from 3D model.
Lower image: Contact length and texture-based polygons are measured in ArcMap.
View to the northeast.
Lithostratigraphic unit: Taob (Loma Barbon Member of Arroyo Ojito Fm.)
Hydrostratigrpahic unit: middle Middle Rio Rancho
UTM coordinates near center of image (NAD83, zone 13): 338275 m E, 3920540 m N

Outcrop for ZP_06

Upper image: Sand and clay body thicknesses and lengths measured from 3D model.
Lower image: Contact length and texture-based polygons are measured in ArcMap.
View to the northeast.
Lithostratigraphic unit: Taob (Loma Barbon Member of Arroyo Ojito Fm.)
Hydrostratigrpahic unit: middle Middle Rio Rancho
UTM coordinates near center of image (NAD83, zone 13): 338275 m E, 3920540 m N