
Outcrop for ZP_04

Upper image: Sand and clay body thicknesses and lengths measured from 3D model.
Lower image: Contact length and texture-based polygons are measured in ArcMap.
View to northeast.
Lithostratigraphic unit: Taob (Loma Barbon Member of Arroyo Ojito Fm.)
Hydrostratigrpahic unit:middle Middle Rio Rancho
UTM coordinates near center of image (NAD83, zone 13): 338061 m E, 3920417 m N



KEY (top):

- Contact -- sand adjacent to clayey unit.
- 1.7 m; 31.3 m — Thickness and length of bed under text

KEY (bottom):

- Analyzed outcrop area
- Contact -- sand on sand
- Contact -- sand adjacent to clayey unit.
- Lithologic interpretation
- Contact -- Lateral gradation of sand into a clayey unit.

