Revised June 1972

TRN142116

STATE ENGINEER OFFICE

WELL RECORD

Section 1. GENERAL INFORMATION

(A) Owner of well THREE RIVERS CATTLE LTD CO Owner's Well No. _____
Street or Post Office Address 118 WEST FIRST STREET
City and State ROSWELL, NM 88201

Well was drilled under Permit No. T-03232 and is located in the:

a _____ ¼ _____ ¼ NE ¼ NE ¼ of Section 3 Township 10S Range 10E N.M.P.M.

b. Tract No. _____ of Map No. _____ of the _____

c. Lot No. _____ of Block No. _____ of the _____
Subdivision, recorded in LINCOLN County.

d. X= _____ feet, Y= _____ feet, N.M. Coordinate System _____ Zone in the _____ Grant.

(B) Drilling Contractor Statewide Drilling, Inc License No. WD-601
Address P. O. Box 458 La Luz, NM 88337

Drilling Began 12/11/97 Completed 12/11/97 Type tools air rotary Size of hole 8 in.

Elevation of land surface or _____ at well is _____ ft. Total depth of well 140 ft.

Completed well is [X] shallow [ ] artesian. Depth to water upon completion of well 60 ft.

Section 2. PRINCIPAL WATER-BEARING STRATA

Depth in Feet From	Depth in Feet To	Thickness in Feet	Description of Water-Bearing Formation	Estimated Yield (gallons per minute)
160	161	1	gravel	15

Section 3. RECORD OF CASING

Diameter (inches)	Pounds per foot	Threads per in.	Depth in Feet Top	Depth in Feet Bottom	Length (feet)	Type of Shoe	Perforations From	Perforations To
5	PVC		0	140	140		40	60
							120	140
6	steel		+1	2	3			

Section 4. RECORD OF MUDDING AND CEMENTING

Depth in Feet From	Depth in Feet To	Hole Diameter	Sacks of Mud	Cubic Feet of Cement	Method of Placement

RECEIVED 97 DEC 15 PM 2:53 STATE ENGINEER OFFICE LAS CRUCES, NEW MEXICO

Section 5. PLUGGING RECORD

Plugging Contractor _____
Address _____
Plugging Method _____
Date Well Plugged _____
Plugging approved by:
_____
State Engineer Representative

No.	Depth in Feet Top	Depth in Feet Bottom	Cubic Feet of Cement
1			
2			
3			
4			

FOR USE OF STATE ENGINEER ONLY

Date Received DECEMBER 15, 1997 Quad _____ FWL _____ FSL _____

File No. T-03232 Use LIVESTOCK Location No. 10S.10E.3.22

Section 6. LOG OF HOLE

Depth in Feet		Thickness in Feet	Color and Type of Material Encountered
From	To		
0	140	140	Red clay, sandstone & gravel

Section 7. REMARKS AND ADDITIONAL INFORMATION

The undersigned hereby certifies that, to the best of his knowledge and belief, the foregoing is a true and correct record of the above described hole.

Mike McMurray
Driller

INSTRUCTIONS: This form should be executed in triplicate, preferably typewritten, and submitted to the appropriate district office of the State Engineer. All sections, except Section 5, shall be answered as completely and accurately as possible when any well is drilled, repaired or deepened When the form is used as a plugging record, only Section 1(a) and Section 5 need be completed.

Thomas C. Turney
State Engineer

Las Cruces Office
133 WYATT DRIVE, SUITE 3
LAS CRUCES, NM 88005

STATE OF NEW MEXICO
STATE ENGINEER OFFICE

Trn Nbr: 142116
File Nbr: T 03232
Well File Nbr: T 03232

Dec. 15, 1997

DELBERT W. NELSON, AGENT
THREE RIVERS CATTLE LTD., CO.
118 WEST FIRST STREET
ROSWELL, NM 88201

Greetings:

Enclosed is your copy of the well record for the above numbered permit, which has been accepted for filing.

Sincerely,

Tom Valverde

Tom Valverde,
Tularosa Basin Supervisor

TJV:eah

(505)524-6161

Enclosure
cc: Santa Fe Office

wellrrcv